



**Supplementary Information**

- 1 Caution RWY incursion imminent: CAT II holding point located direct behind CAT III holding point before turn towards the RWY.

1:10000

